

PREVENTIV

| Nr | Emertimi I materialit     | Njesia | Sasia |
|----|---------------------------|--------|-------|
| 1  | Adapter 110x2"(hollandes) | cope   | 10    |
| 2  | Adapter 90x2              | cope   | 10    |
| 3  | Adapter 75x2              | cope   | 60    |
| 4  | Adapter 63x2              | cope   | 40    |
| 5  | Adapter 63x1 1/2          | cope   | 40    |
| 6  | Adapter 50x2              | cope   | 200   |
| 7  | Adapter 50x1 1/2          | cope   | 200   |
| 8  | Adapter 50x1 1/4          | cope   | 100   |
| 9  | Adapter 40x1 1/2          | cope   | 30    |
| 10 | Adapter 40x1 1/4          | cope   | 40    |
| 11 | Adapter 40x1              | cope   | 40    |
| 12 | Adapter 40x3/4            | cope   | 40    |
| 13 | Adapter 32x1              | cope   | 1000  |
| 14 | Adapter 32x3/4            | cope   | 700   |
| 15 | Adapter 25x1              | cope   | 500   |
| 16 | Adapter 25x3/4            | cope   | 2000  |
| 17 | Adapter 25x1/2            | cope   | 1500  |
| 18 | Adapter 20x3/4            | cope   | 500   |
| 19 | Adapter 20x1/2            | cope   | 1500  |
| 20 | Bashkuese 125             | cope   | 12    |
| 21 | bashkuese 110             | cope   | 150   |
| 22 | bashkuese 90              | cope   | 180   |
| 23 | bashkuese 75              | cope   | 170   |
| 24 | bashkuese 63              | cope   | 180   |
| 25 | bashkuese 50              | cope   | 300   |
| 26 | bashkuese 40              | cope   | 140   |
| 27 | bashkuese 32              | cope   | 300   |
| 28 | bashkuese 25              | cope   | 1600  |
| 29 | bashkuese 20              | cope   | 900   |
| 30 | bashkuese vendi 32        | cope   | 120   |
| 31 | bashkuese vendi 25        | cope   | 100   |
| 32 | bashkuese vendi 20        | cope   | 100   |
| 33 | Fllanxha fikse Ø 250      | cope   | 4     |
| 34 | Fllanxha Ø 400            | cope   | 4     |
| 35 | Fllanxha Ø 300            | cope   | 4     |
| 36 | Fllanxha Ø 200            | cope   | 4     |
| 37 | Fllanxha Ø 150            | cope   | 8     |
| 38 | Fllanxha Ø 100            | cope   | 20    |
| 39 | Fllanxha Ø 50             | cope   | 20    |
| 40 | Fllanxha Ø 80             | cope   | 20    |

PREVENTIV

|    |                      |      |     |
|----|----------------------|------|-----|
| 41 | Fllanxha qorre Ø 250 | cope | 4   |
| 42 | Fllanxha qorre Ø 200 | cope | 8   |
| 43 | Fllanxha qorre Ø 150 | cope | 10  |
| 44 | Fllanxha qorre Ø 100 | cope | 20  |
| 45 | Fllanxha qorre Ø 50  | cope | 10  |
| 46 | Fllanxha qorre Ø 300 | cope | 4   |
| 47 | Fllanxha qorre Ø 400 | cope | 4   |
| 48 | Fllanxha qorre Ø 80  | cope | 20  |
| 49 | elektroda 3.2        | kuti | 200 |
| 50 | elektroda inoksi 3.2 | kg   | 40  |
| 51 | flete guri fresibel  | cope | 800 |
| 52 | elektroda gize 3,2   | cope | 40  |
| 53 | flete sharre         | cope | 800 |
| 54 | Plumb kallep         | kg   | 200 |
| 55 | Guarnicion DN 400    | cope | 6   |
| 56 | Guarnicion DN 300    | cope | 6   |
| 57 | Guarnicion DN 250    | cope | 6   |
| 58 | Guarnicion DN 200    | cope | 10  |
| 59 | Guarnicion DN 150    | cope | 10  |
| 60 | Guarnicion DN 100    | cope | 30  |
| 61 | Guarnicion DN 80     | cope | 30  |
| 62 | Guarnicion DN 50     | cope | 30  |
| 63 | Tabak Gome           | cope | 10  |
| 64 | Bullona M 16x160     | cope | 100 |
| 65 | Bullona M 16x120     | cope | 100 |
| 66 | Bullona M 16x110     | cope | 100 |
| 67 | Bullona M 16x70      | cope | 60  |
| 68 | Bullona M 20x120     | cope | 60  |
| 69 | Bullona M 20x110     | cope | 60  |
| 70 | Bullona M 14x 120    | cope | 60  |
| 71 | Bullona M 14x110     | cope | 60  |
| 72 | Bullona M 14x70      | cope | 60  |
| 73 | Bullona M 16x90      | cope | 200 |
| 74 | Shtang 400           | cope | 4   |
| 75 | Shtang 300           | cope | 4   |
| 76 | Shtang 250           | cope | 4   |
| 77 | Shtang 200           | cope | 6   |
| 78 | Shtang 150           | cope | 8   |
| 79 | Shtang 100           | cope | 30  |
| 80 | Shtang 80            | cope | 30  |
| 81 | Shtang 50            | cope | 20  |

PREVENTIV

|     |                 |                |      |     |
|-----|-----------------|----------------|------|-----|
| 82  | Saracineske     | 200PN 10       | cope | 2   |
| 83  | Saracineske     | 400            | cope | 3   |
| 84  | Saracineske     | 300            | cope | 1   |
| 85  | Saracineske     | 250            | cope | 2   |
| 86  | Saracineske     | 150 PN 10      | cope | 2   |
| 87  | Saracineske     | 100            | cope | 10  |
| 88  | Saracineske     | 80             | cope | 6   |
| 89  | Saracineske     | 50             | cope | 4   |
| 90  | Saracineske     | 2 1/2"         |      | 10  |
| 91  | Saracineske     | 2"             | cope | 90  |
| 92  | Saracineske     | 1 1/2"         | cope | 90  |
| 93  | Saracineske     | 1 1/4"         | cope | 110 |
| 94  | Saracineske     | 1 "            | cope | 80  |
| 95  | Saracineske     | 3/4 "          | cope | 150 |
| 96  | Saracineske     | 1/2 "          | cope | 400 |
| 97  | brryla          | xingato 2"     | cope | 60  |
| 98  | brryla          | 1 1/2"         | cope | 60  |
| 99  | brryla          | 1 1/4"         | cope | 40  |
| 100 | brryla          | 1"             | cope | 20  |
| 101 | brryla          | 3/4"           | cope | 300 |
| 102 | brryla          | 1/2"           | cope | 300 |
| 103 | Elektromanikote | polietilan 90  | cope | 20  |
| 104 | Elektromanikota | polietilan 125 | cope | 10  |
| 105 | Elektromanikote | polietilan 110 | cope | 20  |
| 106 | Elektromanikote | polietilan 140 | cope | 10  |
| 107 | Elektromanikote | polietilan 200 | cope | 8   |
| 108 | Elektromanikote | polietilan 160 | cope | 12  |
| 109 | Elektromanikote | polietilan 220 | cope | 4   |
| 110 | Manikota        | xing 2"        | cope | 30  |
| 111 | Manikota        | xing 1 1/2"    | cope | 60  |
| 112 | Manikota        | xing 1 1/4"    | cope | 40  |
| 113 | Manikota        | xing 1"        | cope | 20  |
| 114 | Manikota        | xing 3/4"      | cope | 100 |
| 115 | Manikota        | xing 1/2"      | cope | 100 |
| 116 | Niples          | 2"             | cope | 50  |
| 117 | Niples          | 1 1/2"         | cope | 60  |
| 118 | Niples          | 1 1/4"         | cope | 40  |
| 119 | Niples          | 1"             | cope | 20  |
| 120 | Niples          | 3/4"           | cope | 300 |
| 121 | Niples          | 1/2"           | cope | 300 |
| 122 | Hollandes       | 2"             | cope | 30  |

PREVENTIV

|     |                                  |      |     |
|-----|----------------------------------|------|-----|
| 123 | Hollandes 1 1/2"                 | cope | 30  |
| 124 | Hollandes 1 1/4"                 | cope | 20  |
| 125 | Hollandes 1"                     | cope | 20  |
| 126 | Hollandes 3/4"                   | cope | 100 |
| 127 | Hollandes 1/2"                   | cope | 100 |
| 128 | Manikota reduktuese 2x1 1/2"     | cope | 30  |
| 129 | Manikota reduktuese 2x1 1/4"     | cope | 20  |
| 130 | Manikota reduktuese 2x1"         | cope | 20  |
| 131 | Manikota reduktuese 2x3/4"       | cope | 60  |
| 132 | Manikota reduktuese 1 1/2x1 1/4" | cope | 30  |
| 133 | Manikota reduktuese 1 1/2x1"     | cope | 40  |
| 134 | Manikota reduktuese 1 1/2x3/4"   | cope | 80  |
| 135 | Manikota reduktuese 1 1/2x1/2"   | cope | 60  |
| 136 | Manikota reduktuese 1 1/4x1 "    | cope | 40  |
| 137 | Manikota reduktuese 1 1/4x3/4"   | cope | 40  |
| 138 | Manikota reduktuese 1 1/4x1/2"   | cope | 40  |
| 139 | Manikota reduktuese 1 x1/2"      | cope | 40  |
| 140 | Manikota reduktuese 3/4x1 "      | cope | 80  |
| 141 | Manikota reduktuese 3/4"x1/2"    | cope | 200 |
| 142 | Litar Lini                       | tufa | 800 |
| 143 | Kundralvalvula 2"                | cope | 50  |
| 144 | Kundralvalvula 1 1/2"            | cope | 60  |
| 145 | Kundralvalvula 1 1/4"            | cope | 70  |
| 146 | Kundralvalvula 1"                | cope | 30  |
| 147 | Kundralvalvula 3/4"              | cope | 60  |
| 148 | Kundralvalvula 1/2"              | cope | 300 |
| 149 | buketona 3/4"                    | cope | 60  |
| 150 | buketona 2"                      | cope | 40  |
| 151 | buketona 1"                      | cope | 100 |
| 152 | buketona 1 1/2"                  | cope | 40  |
| 153 | buketona 1 1/4"                  | cope | 40  |
| 154 | buketona 1/2"                    | cope | 100 |
| 155 | Fashete gize 200x2"              | cope | 5   |
| 156 | Fashete gize 200x80              | cope | 4   |
| 157 | Fashete gize 200x100             | cope | 6   |
| 158 | Fashete gize 160x1 1/2           | cope | 20  |
| 159 | Fashete gize 125x80              | cope | 4   |
| 160 | Fashete gize 125x2"              | cope | 6   |
| 161 | Fashete gize 125x1 1/2"          | cope | 6   |
| 162 | Fashete gize 160x100             | cope | 4   |
| 163 | Fashete gize 160x80              | cope | 6   |

PREVENTIV

|     |                         |      |     |
|-----|-------------------------|------|-----|
| 164 | Fashete gize 160x2"     | cope | 10  |
| 165 | Fashete gize 110x80     | cope | 8   |
| 166 | Fashete gize 110x2"     | cope | 50  |
| 167 | Fashete inoxi 250x100   | cope | 6   |
| 168 | Fashete inoxi 200x100   | cope | 6   |
| 169 | Fashete inoxi 200x80    | cope | 6   |
| 170 | Fashete Inoksi 160x100  | cope | 6   |
| 171 | Fashete inoksi 200x1"   | cope | 5   |
| 172 | Fashete 110x2"          | cope | 30  |
| 173 | Fashete gize 110x1 1/2" | cope | 30  |
| 174 | Fashete gize 110x1 1/4" | cope | 30  |
| 175 | Fashete gize 110x1 "    | cope | 50  |
| 176 | Fashete gize 110x3/4"   | cope | 300 |
| 177 | Fashete 75x2"           | cope | 60  |
| 178 | Fashete 75x1 1/2"       | cope | 60  |
| 179 | Fashete 75x1 1/4"       | cope | 40  |
| 180 | Fashete 75x1"           | cope | 200 |
| 181 | Fashete 75x3/4"         | cope | 400 |
| 182 | Fashete gize 90x2"      | cope | 10  |
| 183 | Fashete gize 90x1 "     | cope | 10  |
| 184 | Fashete gize 90x1 1/2"  | cope | 10  |
| 185 | Fashete gize 90x 3/4"   | cope | 10  |
| 186 | Fashete 63x2"           | cope | 80  |
| 187 | Fashete 63x1 1/4"       | cope | 40  |
| 188 | Fashete 63x1 1/2"       | cope | 40  |
| 189 | Fashete 63x3/4"         | cope | 80  |
| 190 | Fashete 50x1"           | cope | 200 |
| 191 | Fashete 50x3/4"         | cope | 400 |
| 192 | Fashete 50x1/2"         | cope | 400 |
| 193 | Fashete 40x1"           | cope | 60  |
| 194 | Fashete 40x3/4"         | cope | 60  |
| 195 | Fashete 40x1/2"         | cope | 30  |
| 196 | Fashete 32x3/4"         | cope | 40  |
| 197 | Fashete 32x1/2"         | cope | 40  |
| 198 | Fashet Inox 400         | cope | 4   |
| 199 | Fashet Inox 300         | cope | 4   |
| 200 | Fashet gize 300         | cope | 4   |
| 201 | Fashet gize 200         | cope | 30  |
| 202 | Fashet inox 200         | cope | 40  |
| 203 | Fashet inox 160         | cope | 40  |
| 204 | Fashet gize 160         | cope | 40  |

PREVENTIV

|     |                            |      |      |
|-----|----------------------------|------|------|
| 205 | Fashete inox 110           | cope | 200  |
| 206 | Fashete inox 75            | cope | 200  |
| 207 | Tapa 2"                    | cope | 60   |
| 208 | Tapa 1 1/2"                | cope | 60   |
| 209 | Tapa 1 1/4"                | cope | 60   |
| 210 | Tapa 1 "                   | cope | 20   |
| 211 | Tapa 3/4"                  | cope | 100  |
| 212 | Tapa 1/2"                  | cope | 100  |
| 213 | Tapa PPR 20                | cope | 400  |
| 214 | dryna te medhenj           | cope | 820  |
| 215 | dryna te vegjel            | cope | 290  |
| 216 | past filetash              | cope | 200  |
| 217 | Tee xingato 2"             | cope | 20   |
| 218 | Tee xingato 1 1/2          | cope | 20   |
| 219 | tija xingato 1 1/4         | cope | 20   |
| 220 | tija xingato 1"            | cope | 20   |
| 221 | tija xingato 3/4           | cope | 20   |
| 222 | tija xingato 1/2           | cope | 20   |
| 223 | ksula gize 200             | cope | 60   |
| 224 | ksula 150                  | cope | 60   |
| 225 | ksul hidiranti             | cope | 20   |
| 226 | brryla PEHD Ø110           | cope | 40   |
| 227 | brryla tip bashk 90        | cope | 20   |
| 228 | brryla tip bashk 75        | cope | 40   |
| 229 | brryla tip bashk 63        | cope | 50   |
| 230 | brryla tip bashk 50        | cope | 230  |
| 231 | brryla tip bashk 40        | cope | 130  |
| 232 | brryla tip bashk 32        | cope | 200  |
| 233 | brryla tip bashk 25        | cope | 1500 |
| 234 | brryla tip bashk 20        | cope | 1500 |
| 235 | Brryl PE 63x1 1/2          | cope | 40   |
| 236 | Brryl PE 63x2              | cope | 50   |
| 237 | Brryl PE 50x2              | cope | 70   |
| 238 | Brryl PE 50x1 1/2          | cope | 45   |
| 239 | Brryl PE 20x1/2            | cope | 160  |
| 240 | Reduksion gize 150x80      | cope | 2    |
| 241 | Reduksion 200x80           | cope | 2    |
| 242 | Reduksion gize 250x150     | cope | 2    |
| 243 | Reduksion 200x160          | cope | 2    |
| 244 | Reduksion 200x100          | cope | 2    |
| 245 | Reduksion gize, ST 250x200 | cope | 2    |

PREVENTIV

|     |                         |      |      |
|-----|-------------------------|------|------|
| 246 | Reduksion 160x110       | cope | 2    |
| 247 | Reduksion 150x100       | cope | 2    |
| 248 | Reduksion gize 150x80   | cope | 4    |
| 249 | Reduksion PEHD Ø110x75  | cope | 30   |
| 250 | Reduksion 90x75         | cope | 20   |
| 251 | Reduksion 75x63         | cope | 10   |
| 252 | Reduksion 75x50         | cope | 60   |
| 253 | Reduksion 63x50         | cope | 40   |
| 254 | Reduksion 63x40         | cope | 20   |
| 255 | Reduksion 50x40         | cope | 40   |
| 256 | Reduksion 50x32         | cope | 20   |
| 257 | Reduksion 50x25         | cope | 20   |
| 258 | Reduksion 40x32         | cope | 20   |
| 259 | Reduksion 40x25         | cope | 20   |
| 260 | Reduksion 40x20         | cope | 20   |
| 261 | Reduksion 32x25         | cope | 1200 |
| 262 | Reduksion 32x20         | cope | 100  |
| 263 | Reduksion 25x20         | cope | 300  |
| 264 | Reduksion 2x1 1/2       | cope | 20   |
| 265 | Reduksion 2x1 1/4       | cope | 10   |
| 266 | Reduksion 2x1           | cope | 10   |
| 267 | Reduksion 2x3/4         | cope | 60   |
| 268 | Reduksion 2x1/2         | cope | 60   |
| 269 | Reduksion 1 1/2"x1 1/4" | cope | 30   |
| 270 | Reduksion 1 1/2"x1 "    | cope | 20   |
| 271 | Reduksion 1 1/2"x3/4 "  | cope | 20   |
| 272 | Reduksion 1 1/2"x1/2 "  | cope | 60   |
| 273 | Reduksion 1 1/4"x1"     | cope | 20   |
| 274 | Reduksion 1 1/4"x3/4"   | cope | 30   |
| 275 | Reduksion 1 1/4"x1/2"   | cope | 20   |
| 276 | Reduksion 1x 3/4"       | cope | 100  |
| 277 | Reduksion 1x 1/2"       | cope | 100  |
| 278 | Reduksion 1x 3/4"       | cope | 600  |
| 279 | Reduksion 3/4 x 1/2"    | cope | 400  |
| 280 | Tee 110                 | cope | 10   |
| 281 | Tee 90                  | cope | 6    |
| 282 | Tee 75x75x75            | cope | 10   |
| 283 | Tee 63x63x63            | cope | 6    |
| 284 | Tee 50                  | cope | 40   |
| 285 | Tee 40                  | cope | 20   |
| 286 | Tee 32                  | cope | 20   |

PREVENTIV

|     |                     |      |      |
|-----|---------------------|------|------|
| 287 | Tee 25              | cope | 50   |
| 288 | Tee 20              | cope | 30   |
| 289 | fllanxh adapter 125 | cope | 10   |
| 290 | fllanxh adapter 110 | cope | 60   |
| 291 | fllanxh adapter 75  | cope | 30   |
| 292 | fllanxh adapter63   | cope | 10   |
| 293 | fllanxh adapter 50  | cope | 60   |
| 294 | Tub PEHD 300 PN 10  | ml   | 5    |
| 295 | Tub PEHD 250 PN 10  | ml   | 5    |
| 296 | Tub PEHD 200 PN 10  | ml   | 60   |
| 297 | Tub PEHD 160 PN 10  | ml   | 200  |
| 298 | Tub PEHD 110 PN 10  | ml   | 300  |
| 299 | Tub PEHD 110 PN 16  | ml   | 20   |
| 300 | Tub PEHD 125 PN 10  | ml   | 100  |
| 301 | Tub PEHD 125 PN 16  | ml   | 80   |
| 302 | Tub PEHD 90 PN 10   | ml   | 200  |
| 303 | Tub PEHD 90 PN 16   | ml   | 100  |
| 304 | Tub PEHD 75 PN 10   | ml   | 400  |
| 305 | Tub PEHD 50 PN 16   | ml   | 100  |
| 306 | Tub PEHD 50 PN 10   | ml   | 600  |
| 307 | Tub PEHD 40 PN 16   | ml   | 100  |
| 308 | Tub PEHD 40 PN 10   | ml   | 300  |
| 309 | Tub PEHD 32 PN 10   | ml   | 500  |
| 310 | Tub PEHD 25 PN 10   | ml   | 4100 |
| 311 | Tub PEHD 20 PN 10   | ml   | 3100 |
| 312 | Tub PEHD 63 PN 10   | ml   | 100  |
| 313 | Tub PEHD 63 PN16    | ml   | 100  |
| 314 | Mates uji 1/2"      | cope | 1000 |
| 315 | Mates uji 1"        | cope | 5    |
| 316 | Tub xngato 2"       | ml   | 12   |
| 317 | Tub xngato 1 1/2"   | ml   | 12   |
| 318 | Tub xngato 1 1/4"   | ml   | 12   |
| 319 | Tub xngato 1 "      | ml   | 24   |
| 320 | Tub xngato 3/4 "    | ml   | 36   |
| 321 | Tub xngato 1/2 "    | ml   | 36   |
| 322 | Tub xngato 80       | ml   | 12   |
| 323 | Mishelator 1/2"     | cope | 3    |
| 324 | Aspirator           | cope | 2    |